



Newport

## **ESP Motion Controllers**

### **CD Installation Software**

Version 2.3

Revision Date: May 4, 2005

### **Newport Corp. World Wide Web Server**

You can access a variety of Newport Corporation information sources via the Newport Web Server, <http://www.newport.com>.

### **Technical Support**

Please review the User's Manual first if you are experiencing difficulties with the product. The following Technical Support information is listed below if you still need help.

Tel: 1-800-222-6440

Fax: 1-949-253-1479

Email: <mailto:rma.service@newport.com>

Internet: <http://support.newport.com>

This Installation Contains:

### **Utilities**

<b>ESP-Util</b>	<b>Version 4.20</b>
<b>ESP-Tuning</b>	<b>Version 3.04</b>
<b>ESP-Wizard</b>	<b>Version 3.30</b>
<b>Smartstage database</b>	<b>Version 5.20</b>
<b>ESP-Help</b>	

### **Device Drivers**

<b>Win95 Driver for ESP6000</b>	<b>Version 2.07</b>
<b>Win98 Driver For ESP6000</b>	<b>Version 3.00</b>
<b>Win98 Driver For USB</b>	<b>Version 1.00</b>
<b>Win NT Driver for ESP6000</b>	<b>Version 2.07</b>
<b>Win 2000 Driver for ESP6000</b>	<b>Version 3.00</b>
<b>Win 2000 Driver for USB</b>	<b>Version 1.00</b>

### **Firmware**

<b>ESP100 Firmware</b>	<b>Version 3.03</b>
<b>ESP100 FPGA Firmware</b>	<b>Version 3.01</b>
<b>ESP300 Firmware</b>	<b>Version 3.09</b>
<b>ESP300 FPGA Firmware</b>	<b>Version 3.02</b>
<b>ESP6000 Firmware</b>	<b>Version 3.03</b>
<b>ESP7000 Firmware</b>	
<b>CPU Firmware</b>	<b>Version 3.04</b>
<b>DSP Firmware</b>	<b>Version 3.04</b>

### **Manuals**

<b>ESP100</b>	<b>29754-01 Rev. B</b>
<b>ESP300</b>	<b>28187-02 Rev. F</b>
<b>ESP6000</b>	<b>22945-01 Rev. E</b>
<b>ESP7000</b>	<b>28314-01 Rev. E</b>

## **Samples**

### **LabView Samples:**

**ESP-ASCII.llb**

#### **PCI Interface:**

**ESP6000(LV4).llb**

**Example1.vi**

**Example2.vi**

**Example3.vi**

**Example, Ascii Cycle.vi**

**Example, Raster.vi**

**Readme.pdf**

#### **RS232 Interface:**

**ESP example 1.vi**

#### **GPIB Interface:**

**Esp\_gpib\_init\_system.vi**

**Esp\_gpib\_comm\_ASCII.vi**

**ESP300 GPIB Comm Test.vi**

**ESP300 GPIB LP Sample.vi**

### **Stored Motion Program Samples:**

**Cycle.txt**

**RasterScan.txt**

**Line.txt**

**Circle.txt**

**Eight.txt**

### **Visual Basic Samples:**

**ESP-Terminal**

**ESP-USB**

**ESP-Comm**

### **Visual C++ Samples:**

**Daq Demo**

**RS232Comm**

## **Bug Fixes:**

### Version 2.1

- 1.) Script was telling users to restart after installation. This was not necessary
- 2.) If you chose any directory except the default some selected files would not be copied.
- 3.) Script was copying file advapi32.dll to the System32 directory. This could create a fatal error with Windows NT and the kernel32.dll
- 4.) Msi.dll being installed on Windows NT has adverse causes MS office to stop working