
M Band transmission
= Curve used by AQE procedure
= Curve from Barr spreadsheet
Transmission (%)
120
100
80
60
40
20
0
2000
3000
4000
5000
6000
7000
Wavelength